



Cooling Tower Fills Replacement Solution by Daikin



Cooling Towers are a critical component in a chiller plant wherein heat from the airconditioned space is rejected to the atmosphere and a chiller plant cannot function without it. Cooling towers are also a major contributor to energy efficiency of the chillers they serve.

The most important component of a cooling tower is the fill. Its ability to promote the maximum surface area and the max contact time between air and water determines the efficiency of the cooling tower. It must promote the air-water contact and least possible restrictions to air flow.

Let our energy experts help you save energy and improve your cooling tower performance

Assessment of your cooling towers

Proposal with solutions to improve your cooling tower performance

Fill inspection to see if replacement is required Suitable fill selections

Supply and Installation of fills and startup

When to Replace Fills?

- Increased Energy Consumption
- Uneven Water Distribution
- Sagging fill packs
- Damaged Support Grids
- Calcium Built-up
- Higher leaving water Temperature

Impact of condenser water temperature on the chiller efficiency

Damaged cooling tower fills results in higher water temperature leaving the cooling tower. This has a direct negative impact on the chiller efficiency and on the cooling capacity of the chilled water plant.

Consider a situation wherein the chiller capacity is neck to neck with peak summer cooling needs. Deteriorated cooling tower fills will in most cases result in high cooling water inlet temperature to the condenser, thereby reducing cooling capacity delivery from chiller and increasing energy consumption and even leading to surging of a centrifugal chiller.

The below graph shows an example of the impact of higher condenser water temperature on chiller efficiency (kW/TR) for a new chiller. It could be worst in actual operation in an existing chiller.

Impact of damaged/inefficient fills on Chiller power consumption



The present publication is drawn up by way of information only and does not constitute an offer binding upon Daikin MEA. Daikin MEA has compiled the content of this publication to the best of its knowledge. No express or implied warranty is given for the completeness, accuracy, reliability or fitness for particular purpose of its content and the products and services presented therein. Specifications are subject to change without prior notice. Daikin MEA explicitly rejects any liability for any direct or indirect damage, in the broadest sense, arising from or related to the luse and/or interpretation of this publication. All content is copyrighted by Daikin MEA

DAIKIN MIDDLE EAST AND AFRICA FZE

P.O. Box 18674, Plot MO0426, JAFZA North, Jebel Ali Free Zone, Dubai, UAE | Tel: +971 (0) 4 815 9300 | Fax: +971

E-mail: info@daikinmea.com

Web: www.daikinmea.com

Toll Free: 800-DAIKIN (324546)

